

# Zone Report

Report Date: 11/28/2019

---

U888000101      Ultima 844/862/880

Zone No	Module No	Description
45	100	CODEPAD MEDICAL
46	110	CODEPAD FIRE
9	120	-PANIC KEYFOB
10	120	-PANIC KEYFOB
11	120	-PANIC KEYFOB
12	120	-PANIC KEYFOB
13	120	-PANIC KEYFOB
14	120	-PANIC KEYFOB
15	120	-PANIC KEYFOB
16	120	-PANIC KEYFOB
17	120	-PANIC KEYFOB
18	120	-PANIC KEYFOB
19	120	-PANIC KEYFOB
20	120	-PANIC KEYFOB
21	120	-PANIC KEYFOB
22	120	-PANIC KEYFOB
23	120	-PANIC KEYFOB
24	120	-PANIC KEYFOB
25	120	-PANIC KEYFOB
26	120	-PANIC KEYFOB
27	120	-PANIC KEYFOB
28	120	-PANIC KEYFOB
29	120	-PANIC KEYFOB
30	120	-PANIC KEYFOB
31	120	-PANIC KEYFOB
32	120	-PANIC KEYFOB
33	120	-PANIC KEYFOB
34	120	-PANIC KEYFOB
35	120	-PANIC KEYFOB
36	120	-PANIC KEYFOB
37	120	-PANIC KEYFOB
38	120	-PANIC KEYFOB
39	120	-PANIC KEYFOB
40	120	-PANIC KEYFOB
41	120	CODEPAD PANIC

64000	121 DURESS
0	300 FUSE
30	301 MAINS POWER
64000	307 SENSOR SELF TEST FAILURE
31	309 BACKUP BATTERY
1	355 RF RECEIVER JAMMING
2	355 RF RECEIVER TAMPER SWITCH
3	355 RF RECEIVER FAILURE
42	421 CODE RETRY LIMIT EXCEEDED
44	602 PERIODIC TEST SIGNAL
47	602 TEST REPORT AFTER SIREN RESET
64000	607 WALK TEST
45	1100 CODEPAD MEDICAL
46	1110 CODEPAD FIRE
41	1120 CODEPAD PANIC
64000	1121 DURESS
0	1300 FUSE
30	1301 MAINS POWER
64000	1307 SENSOR SELF TEST FAILURE
31	1309 BACKUP BATTERY
1	1355 RF RECEIVER JAMMING
2	1355 RF RECEIVER TAMPER SWITCH
3	1355 RF RECEIVER FAILURE
42	1421 CODE RETRY LIMIT EXCEEDED
44	1602 PERIODIC TEST SIGNAL
47	1602 TEST REPORT AFTER SIREN RESET
64000	1607 WALK TEST