

Type Report

Report Date: 12/07/2019

IRNCBASETT IR Fast Inception

Type No	Description	Action Plan
3085	Restore Power Supply	Restoral, No Alarm
3341	Power Supply Failure	System Alarm
3597	Tamper Power Supply	System Alarm
3853	Isolate Power Supply	System Alarm
4115	Restore AC Fail	Restoral, No Alarm
4116	Restore Battery Test	Restoral, No Alarm
4117	Restore Short Detected	Restoral, No Alarm
4118	Restore Power Supply	Restoral, No Alarm
4119	Restore User Duress	Restoral, No Alarm
4371	AC Fail	AC Fail
4372	Battery Test	System Alarm
4373	Short Detected	System Alarm
4374	Power Supply Failure	System Alarm
4375	User Duress	Panic Alarm
4627	Tamper AC Fail	System Alarm
4628	Tamper Battery Test	System Alarm
4629	Tamper Short Detected	System Alarm
4630	Tamper Power Supply	System Alarm
4631	Tamper User Duress	System Alarm