Report Date: 28/11/2019

M599000101 MULTICOM 5 PLUS 99 Template

Type No	Description	Action Plan
755	EVENT NOT DEFINED	General Alarm
756	EVENT NOT DEFINED	General Alarm
927	EVENT NOT DEFINED	General Alarm
928	EVENT NOT DEFINED	General Alarm
950	EVENT NOT DEFINED	General Alarm
1755	EVENT NOT DEFINED	General Alarm
1756	EVENT NOT DEFINED	General Alarm
1950	EVENT NOT DEFINED	General Alarm
2755	EVENT NOT DEFINED	General Alarm
2756	EVENT NOT DEFINED	General Alarm
2950	EVENT NOT DEFINED	General Alarm