

Type Report

Report Date: 11/28/2019

TXPR000101 Texecom Premier 412\816\832

Type No	Description	Action Plan
121	DURESS	Medical Alarm
139	CONFIRMED ALARM	General Alarm
140	ALARM	General Alarm
144	TAMPER	General Alarm
220	MONITORED ALARM	General Alarm
300	AUXILIARY POWER	A/C Failure
301	MAINS POWER	A/C Failure
302	BACKUP BATTERY	Low Battery
333	EXPANDER\REMOTE	Low Battery
351	TELEPHONE LINE	Low Battery
354	FAIL TO COMMUNICATE	System Alarm
355	RADIO SUPERVISION FAULT	System Alarm
356	COMMUNICATION PORT FAULT	System Alarm
373	FIRE ZONE	Low Battery
380	TROUBLE	Low Battery
384	FOB LOW BATTERY	System Alarm
401	DISARMED	Opening (Unset), No Alarm
403	AUTOMATIC	Opening (Unset), No User
405	AUTOMATIC ARM DEFERRED	System Alarm
406	AFTER ALARM (CANCEL)	Opening (Unset), No User
407	BY REMOTE	Opening (Unset), No User
459	RECENT	Closing (Set), No User
574	GROUP	Zone Bypass
601	MANUAL TEST TRANSMISSION	Test Report
602	PERIODIC TEST SIGNAL	System Alarm
623	LOG CAPACITY ALERT (80PERCENT)	System Alarm
625	DATE\TIME CHANGED	System Alarm
1121	DURESS	Restoral, No Alarm
1139	CONFIRMED ALARM	Restoral, No Alarm
1140	RESTORE	Restoral, No Alarm
1144	TAMPER	Restoral, No Alarm
1220	MONITORED ALARM	Restoral, No Alarm
1300	AUXILIARY POWER	Restoral, No Alarm
1301	MAINS POWER	Restoral, No Alarm
1302	BACKUP BATTERY	Restoral, No Alarm
1321	BELL OUTPUT	Low Battery

1333	EXPANDER\REMOTE	Restoral, No Alarm
1351	TELEPHONE LINE	Restoral, No Alarm
1373	FIRE ZONE	Restoral, No Alarm
1380	TROUBLE	Restoral, No Alarm
1401	ARMED	Closing (Set), No Alarm
1403	AUTOMATIC	Closing (Set), No User
1407	BY REMOTE	Closing (Set), No User
1408	BY QUICK KEY	Closing (Set), No User
1574	GROUP	Zone Bypass